

Chevrolet Captiva 2.0VCDi 150HP

1. Box type: VT101201.
2. Find plug for rail pressure sensor. Disconnect it and connect box adapter between.

