

Honda CR-V 2.2i-DTEC 150HP

1. Box Type: VT301200-003
2. Find common rail sensor and map sensor plugs, disconnect them and connect box adapters between.

